

SITE INSPECTION REVIEW FORM

SITE NAME: MAUNABO SOLID WASTE DISPOSAL

ALIASES: \_\_\_\_\_

SITE I.D.#: PRD980512420

<u>ITEM</u>	<u>COMPLETE</u> <u>YES</u>	<u>?</u> <u>NO*</u>
SITE LOCATION (INCLUDING MAP)	<input checked="" type="checkbox"/>	___
SITE BACKGROUND	<input checked="" type="checkbox"/>	___
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	<input checked="" type="checkbox"/>	___
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<input checked="" type="checkbox"/>	___
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	<input checked="" type="checkbox"/>	___
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<input checked="" type="checkbox"/>	___
POTENTIAL FOR DIRECT CONTACT	<input checked="" type="checkbox"/>	___
CONCLUSIONS + RECOMMENDATIONS	<input checked="" type="checkbox"/>	___
REFERENCES	<input checked="" type="checkbox"/>	___

HRS PRE-SCORE: PRELIMINARY SCORE = 21.35  
PROJECTED SCORE = 38.29 } Medium

397303



COMMENTS:

This site is recommended for an LST  
due to the priority pollutants  
found in the soil which could  
contaminate GW that is used  
for drinking.

REVIEWED BY:

Sandra L. Huxley

DATE:

6/29/89

\*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS